



JSW Steel (USA) Inc.
500 East McKinney Rd
Baytown, TX-77523

FORM#: PIP-011A
Rev: 2
Date: 08/08/2017

LOAD TALLY

Load #: 158769
TRUCK 24114
Shipper: TONI TERRY
Date Shipped: 08/26/2026
Freight: Customer Pickup
Dunnage(pcs): 0

Carrier Name: PAUL TRANSPORT
Qty Shipped (pcs): 6
Len Shipped (ft): 243.19
Wgt Shipped (lbs): 38,345.58
Empty Truck Wt (lbs): 30,160.00
Gross Wt (lbs): 68,505.58

Comments: RELEASE 2497915

Cust Ord #	Cust Rel #	Bill #	JPM Ord #	Wall (in)	OD (in)	Grade
324396		2606267985-01	JPM37985	0.500	30.00	X65M_PSL2
#	Length	Weight	Heat	Pipe#	Coating	
1	40.76	6,426.93	S37473	K26078621	Bare	
2	40.83	6,437.97	S37483	K26078808	Bare	
3	39.16	6,174.65	S37473	K26078905	Bare	
4	40.78	6,430.09	S37477	K26079014	Bare	
5	40.83	6,437.97	S37461	K26079243	Bare	
6	40.83	6,437.97	S37473	K26079571	Bare	

The pipe listed above have been loaded and checked as serviceable and no visible damages unless specifically stated otherwise.

ALL PIPES LEFT JSW STEEL (USA), INC., UNDAMAGED AS SHOWN ABOVE. ANY DAMAGE MUST BE NOTED PRIOR TO REMOVAL OF PIPE FROM CONVEYANCE WITH SUFFICIENT TIME TO ALLOW JSW STEEL (USA), INC., TO INSPECT AND VERIFY SAID DAMAGE. PLEASE NOTE JSW STEEL (USA), INC., AT THEIR DISCRETION MAY SO ADVISE THEY WAIVE THEIR RIGHT TO INSPECTION. THIS WAIVER MUST BE DOCUMENTED IN WRITING, AND NO CLAIMS WILL BE PROCESSED WITHOUT AN INSPECTION REPORT OR WAIVER OF INSPECTION.

Note: Proper securement of load is the sole responsibility of the truck driver.

Pipes Visually Inspected by:

Head Loader: RE

QC Inspector: RE

Truck Driver: _____

Comments: _____

ALEXA
ALEXA



JSW Steel (USA) Inc.
500 East McKinney Rd
Baytown, TX-77523

FORM#: PIP-011A
Rev: 2
Date: 08/08/2017

LOAD TALLY

Load #: 158768
TRUCK 02
Shipper: TONI TERRY
Date Shipped: 08/26/2026
Freight: Customer Pickup
Dunnage(pcs): 0

Carrier Name: JOSDA
Qty Shipped (pcs): 7
Len Shipped (ft): 283.42
Wgt Shipped (lbs): 44,688.95
Empty Truck Wt (lbs): 31,180.00
Gross Wt (lbs): 75,868.95

Comments: RELEASE 2497915

Cust Ord #	Cust Rel #	Bill #	JPM Ord #	Wall (in)	OD (in)	Grade
324396		2606267985-01	JPM37985	0.500	30.00	X65M_PSL2
#	Length	Weight	Heat	Pipe#	Coating	
1	40.83	6,437.97	S37507	K26078239	Bare	
2	40.83	6,437.97	S37476	K26078931	Bare	
3	38.46	6,064.28	S37475	K26078948	Bare	
4	40.83	6,437.97	S37455	K26079103	Bare	
5	40.83	6,437.97	S37474	K26079464	Bare	
6	40.83	6,437.97	S37473	K26079537	Bare	
7	40.81	6,434.82	S37465	K26079928	Bare	

The pipe listed above have been loaded and checked as serviceable and no visible damages unless specifically stated otherwise.

ALL PIPES LEFT JSW STEEL (USA), INC., UNDAMAGED AS SHOWN ABOVE. ANY DAMAGE MUST BE NOTED PRIOR TO REMOVAL OF PIPE FROM CONVEYANCE WITH SUFFICIENT TIME TO ALLOW JSW STEEL (USA), INC., TO INSPECT AND VERIFY SAID DAMAGE. PLEASE NOTE JSW STEEL (USA), INC., AT THEIR DISCRETION MAY SO ADVISE THEY WAIVE THEIR RIGHT TO INSPECTION. THIS WAIVER MUST BE DOCUMENTED IN WRITING, AND NO CLAIMS WILL BE PROCESSED WITHOUT AN INSPECTION REPORT OR WAIVER OF INSPECTION.

Note: Proper securement of load is the sole responsibility of the truck driver.

Pipes Visually Inspected by:

Head Loader: RF

QC Inspector: RF

Truck Driver: _____

Comments: _____

FELIX